



**New 170 amp Alternator**

- Main Truss Bracket
- Tensioner With Bracket
- Power Steering Bracket
- Polished compressor
- Polished "170 amp alternator"
- Polished Front Runner belt tensioner cover
- Polished Compressor Clutch Cover
- Hardware And Spacer Kit Stewart Warner High Volume Alum Water Pump



342311  
\$50

- Crankshaft Pulley
- Water Pump Pulley
- Power Steering Pulley
- Serpentine Drive Belt

**Power Steering Accessories**



- Power Steering Hard Line Kit **852000** \$82
- SS Hose Kit for early GM (1965-81) **852008** \$177
- SS Hose Kit for Mustang II **852009** \$182
- Flow control valve for Mustan **852001** \$31

- SB Ford S/S Dip Stick & Tube Kit (for front sump pan) **39900-SFA** \$79.95



**Chevrolet Front Runner**

174015	SB "Bright" w/power steering	\$2295
174008	SB "Black" w/power steering	\$2245
174058	BB "Bright" w/power steering	\$2410
174048	BB "Black" w/power steering	\$2380
174014	LS "Bright" w/power steering	\$2925
174011	LS "Black" w/power steering	\$2825
174027	LS Low Profile "Bright" w/power steering	\$3115
174029	LS Low Profile "Black" w/power steering	\$3015
174013	LS7 "Bright" w/power steering	\$2925
174013	LS7 "Black" w/power steering	\$2825


- Chrome Up-grade on Polished \$100
- Chrome Up-grade on Black \$150
- Power Steering Delete - Deduct \$175

**Ford Front Runner**

174100	SB "Bright" w/power steering	\$2670
175103-SFA	SB "Bright" w/o power steering	\$2405
174101	SB "Black" w/power steering	\$2645
174020	Ford Coyote w/power steering	\$1430

**WARNING:** This product can expose you to chemicals including lead, which is known to the State of California to cause cancer and birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov)

**100R 200L**



A/C bkt for SWP, Passenger Side, SB  
**100R**

A/C bkt for SWP, Driver Side, SB  
**100L**

A/C bkt for LWP - Passenger Side, SB  
**101R**

A/C bkt for LWP - Driver's Side, SB  
**101L**

Alt bkt for SWP - Driver's Side, SB  
**200L**

Alt bkt for LWP - Driver's Side, SB  
**201L**

A/C bkt for SWP, 87 & later cast iron vortex heads  
**129R**

Alt bkt for SWP, 87 & later cast iron vortex heads  
**228L**

**104R 204L**



A/C bkt for Big Block -short W/P-Passenger Side  
**104R**

Alt. bkt for Big Block - short W/P - Driver's Side  
**204L**

York to Sanden Bracket Adaptor  
**CB-Y**



**\$65**



Universal Compressor Bracket  
**CB-U**

**\$48**



**\$98**

**\$98**

**\$98**

**\$98**

**\$87**

**\$87**

64-68 Chevelle A/C bkt, SWP, SB

**113R** **\$98**

64-68 Chevelle alt & p/s bkt, SWP, SB

**600L** **\$195**


64-68 Chevelle A/C bkt, SWP, Big Block

**118R** **\$98**

64-68 Chevelle alt & p/s bkt, SWP, Big Block

**601L** **\$180**

**113R 213L**



A/C bkt for SWP - Pass. Side - Low Profile - SB

**113R** **\$98**

A/C bkt for SWP - Driver's Side Low Profile-SB

**113L** **\$98**

A/C bkt for LWP - Pass. Side - Low Profile - SB

**123R** **\$98**

A/C bkt for LWP-Driver's Side - Low Profile-SB

**119L** **\$98**

Alt bkt for SWP - Driver Side - Low Profile - SB

**213L** **\$98**

Alt bkt for LWP - Driver Side - Low Profile - SB

**223L** **\$98**


A/C bkt for SWP - Pass Side - Low Profile - BB

**118R** **\$98**

A/C bkt for SWP - Driver's Side-Low Profile -BB

**218L** **\$98**

**WARNING:** This product can expose you to chemicals including lead, which is known to the State of California to cause cancer and birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov)



**400L**


Y Block



**Self Contained P/S Pump Bracket**


- Alt & A/C Bkt for 55-62 235 6 cyl  
**301L** **\$145**
- Alt & A/C Bkt for 54 & earlier 216 & 261 6 cyl  
(3/8 in belt)  
**15273-VCB** **\$149**
- A/C Bkt for 63-84 6 cyl  
**15249-VCB** **\$159**
- A/C Bkt for 78-84 250 w/H.E.I.  
**15250-VCB** **\$349**

<b>400L</b>	<b>SBC/SWP</b>	<b>\$78</b>
<b>402L</b>	<b>SBC/LWP</b>	<b>\$78</b>
<b>403L</b>	<b>BBC/SWP</b>	<b>\$78</b>
<b>802409</b>	<b>SBF/289/302/351W</b>	<b>\$72</b>
<b>802410</b>	<b>Ford 200/250 6 cyl</b>	<b>\$72</b>
<b>802411</b>	<b>Ford 292/312 Y Block</b>	<b>\$128</b>
<b>802412</b>	<b>Mopar 318/340/360</b>	<b>\$72</b>




Pontiac A/C 64-79 bkt for 326 - 455  
**141001-PPA** **\$109**

R-4 to Sanden Compressor Adaptor Bkt. for  
1979-1995 GM Truck (works with stock height  
valve covers)  
**CB-R4** **\$65**



A/C Bkt for 1967-90 Olds  
fits 260-425  
**141008** Passenger Side **\$119**  
**141009** Driver Side **\$119**

**WARNING:** This product can expose you to chemicals including lead, which is known to the State of California to cause cancer and birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov)




383-440 Mopar Compressor and Alt Brt  
**161002**

\$249

289-351W  
Driver Side  
Compressor  
Bracket  
**131107**

\$99



Alternator Bracket  
for SB Ford  
**131112**


\$70

289-351W Driver Side Power Steering Bracket  
(add on kit)  
**131108**

\$91

Ford FE (65 & up)  
Drivers Side AC  
Bracket  
**131005**

\$109



Ford "Y" Block Alt & A/C Bracket  
(need 2 groove add on crank pulley BOR-801150  
and rear exit compressor)  
**131111**

\$150

**105L**



A/C bkt for Small Block Ford - Driver's Side, fits  
289, 302, & 351 Windsor  
**105L**

\$99



65-81 170/200 Ford 6 Cyl Alt & A/C Bracket  
**316R**

\$145

223 Ford 6 cyl AC & GM alt Bracket with crank  
pulley  
**131138**

\$225

240-300 Ford 6 Cyl AC & GM Alt Bracket with  
crank pulley  
**131119**

\$225



37-48 Ford A/C & Alt Bkt for 5/8" wide belt  
**312**

\$227

49 Car & 48-53 Truck A/C & Alt Bkt for 5/8"  
wide belt (off-set water neck reg.)  
**313**

\$227

50-53 Car AC & Alt Bkts for 3/8" belt (2-off-set  
water necks reg.)  
**314**

\$227

**WARNING:** This product can expose you to chemicals including lead, which is known to the State of California to cause cancer and birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov)

## LS Brackets



This bracket system is designed to mount an after-market Sanden A.C. compressor to the popular LS series engines utilizing the factory alternator and power steering pump accessories. Bolts to head and water pump. Works well in vehicles with low hood clearance--1947 & up Trucks, 50-60's cars, etc. Bracket kit includes: Steel A.C. mounting brackets, mounting hardware, and heavy duty automatic belt tensioner and illustrated instructions for easy installation.

LS Truck & 2010 & up Camaro AC bkt (3")

**CB-LS1** \$185

LS Camaro/Firebird (F Body 98-02)

AC Bracket (2 1/4")  
**K10156** \$197

LS Corvette AC Bracket (1 1/2")

**K10143** \$197

#### LS Balancer Dimensions

\*With a straight edge placed across the front of the balancer; measure to the machined surface of the balancer.\***Note: Balancer retaining bolt does not need to be removed**

**1999-2013 Truck & 2010 & up Camaro**


3" measurement

**98-2002 Camaro/Firebird & 2004-2006 GTO**

2 1/4" measurement

**1997-2013 Corvette**

1 1/2" measurement



#### For Sanden SD7B10 - 7176 mini-compressor

Mounts small Sanden AC compressor in stock location, low on passenger's side  
Works great with LSA and other supercharged engines with no room for upper compressor mounting

- Uses the original 4-groove area of the balancer
- Tensioner and 4-rib belt are included
- Overall width from crank center line - 12"
- Clears most after-market motor mount adapter plates which put the engine in "stock" location
- May not work with Holley Gen 1 or Gen 2 Camaro engine mounts

LS Corvette/LSA harmonic balancer

**K10355** \$247

F-Body (98-02)/GTO LS Mini-AC Brk kit

Low-mount AC bracket for engines with F-Body(98-02)/GTO (04-06) accessory drive harmonic balancer

**K10420** \$247

Truck/2010-15 Camaro LS Mini-AC brk kit

Low-mount AC bracket for engines with 99-13 truck/2010-15 Camaro harmonic balancer

**K10421** \$247

**WARNING:** This product can expose you to chemicals including lead, which is known to the State of California to cause cancer and birth defects or other reproductive harm. For more information go to [www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov)